TRAFFIC CRASH REPORT CHP 555 Page 1 (Rev. 3-20) OPI 060

Page 1

	-	•	,													•
SPECIAL	L CONDITIONS			NO. IN	NJURED	HIT & R	UN FELONY				JDICIAL DIS			AL REPORT	NUMBER	
FAIA	AL							DAVI	S	,	YOLO S	UPERIOR CO	URT 22	-02347		
				NO. K	ILLED	HIT & R	UN MISD	COUNTY		REPOR	RTING DIST	RICT BEAT	DAY	OF WEEK	TOW	/ AWAY
				1				YOLO)	UCI	D	UCD	W	EDNESI	DAY _	$YES \boxed{X} \; NO$
	COLLISION OC	CURRED (ON:	'		•				MO DAY		TIME	NCIC		OFFICER I	.D.
L	HUTCHIS	SON DE	₹							05/25/202	22	0800	CA	A057010	0 127	
CA	MILEPOST INF	ORMATION	N				GPS Coord	dinates					PHO ⁻	TOGRAPHS	BY:	NONE
A T							LATIT	TUDE 3	8.53921,	LONGITU	DE -121.	75880	SC	HWENI	n	
0	X AT INTE	RSECTION	WITH D	AIRY RI)							STATE HWY REL	30	U M EINI	D	
N	OR											YES X NO	o			
PARTY	DRIVERS LICE	NSE NUME	BER	STA	TE C	CLASS	AIRBAG	SAFET	TY EQUIP.	VEH. YEAR	MAKE/MO	DEL/COLOR		LICENSE	NUMBER	STATE
1							P	W			ELCY	/BLK				CA
DRIVER	NAME						1									
										OWNER NAM	Ė		X SAME	AS DRIVER		
PEDEST	STREET ADDR	ESS								1						
										OWNER ADDI	RESS		X SAME	AS DRIVER	!	
PKD VEH	CITY/STATE/ZI	Р								1						
										DISPOSITION	OF VEHICLI	E ON ORDERS OF:	X OFFICI	ER	DRIVER 0	OTHER
BICYLST	SEX HAIF	₹	EYES	HEIGHT	WEIGH	IT	BIRTHDAT	ΓE	RACE	DAVIS F	D EVID	ENCE				
X										PRIOR MECH	ANICAL DEF	ECTS: X	NONE APPARE	:NT	REFER TO NAR	RATIVE
OTHER	HOME PHONE				BUSIN	ESS PHON	E			VEHICLE IDEI	NTIFICATION	NUMBER:				
										VEHICLE	TYPE	DESCRIBE VEHIC	CLE DAMAGE		SHADE IN DAI	MAGED AREA
OPER-	INSURANCE C.	ARRIER				POLIC	Y NUMBER			04		UNK.	NONE N	MINOR]
ATOR												X MOD.	MAJOR F	ROLL-OVER		F R O
	DIR OF TRAVE	L ON ST	REET OR H	IGHWAY	L	ANE	THRU	TOTAL	SPD LIMIT	CA		DOT				N T
	Е	HU'	TCHISO	N DR			LANES	LANES 2	25	CAL-T	1	TCP/PSC I	MC/MX			
PARTY	DRIVERS LICE	NSE NUME	BER	STA	TE C	CLASS	AIRBAG	SAFET	TY EQUIP.	VEH. YEAR	MAKE/MO	DEL/COLOR		LICENSE	NUMBER	STATE
2										2011	AUTO	/WHI-BLU		13531	134	CA
DRIVER	NAME	•														
X										OWNER NAM	Ē		SAME	AS DRIVER	<u> </u>	1
PEDEST	STREET ADDR	ESS								UC DAV	IS FLEE	T SERVICES				
										OWNER ADDI	RESS		SAME	AS DRIVER	Į.	
PKD VEH	CITY/STATE/ZI	Р								ONE SH	IELDS A	VE DAVIS C	A 95618			
										DISPOSITION	OF VEHICLI	E ON ORDERS OF:	X OFFICI	ER	DRIVER 0	OTHER
BICYLST	SEX HAIF	₹	EYES	HEIGHT	WEIGH	IT	BIRTHDAT	TE	RACE	PARKEL	AT UC	DAVIS FLEE	Т			
										PRIOR MECH	ANICAL DEF	ECTS: X	NONE APPARE	:NT	REFER TO NAR	RATIVE
OTHER	HOME PHONE				BUSIN	ESS PHON	E			VEHICLE IDEI	NTIFICATION	NUMBER: 5VC	CACLLE4B	H21167	9	
ш										VEHICLE	TYPE	DESCRIBE VEHIC	CLE DAMAGE		SHADE IN DAI	MAGED AREA
OPER- ATOR	INSURANCE C						Y NUMBER			26		UNK.	NONE X	MINOR		F R
	UC DAVI	S				SEL	F INSUR	.ED				MOD.	MAJOR F	ROLL-OVER	'] [[[0
	DIR OF TRAVE					ANE	THRU LANES	TOTAL LANES		CA 54102		DOT				N T
	Е		TCHISO			2	1	2	25	CAL-T			MC/MX			
PARTY	DRIVERS LICE	NSE NUME	BER	STA	TE C	CLASS	AIRBAG	SAFET	TY EQUIP.		MAKE/MO	DEL/COLOR		LICENSE	NUMBER	STATE
3																
DRIVER	NAME (FIRST,	MIDDLE, L	AST)													
										OWNER NAM	E		SAME	AS DRIVER		
PEDEST	STREET ADDR	ESS								0140150 4001						
										OWNER ADDI	RESS		SAME	AS DRIVER		
PKD VEH	CITY/STATE/ZI	۲								DIOD COITION	051/51801					
	SEV III.		EVEC	HEIGHT	WE:O:	IT.	DIDTUD		BACE	DISPOSITION	OF VEHICLI	E ON ORDERS OF:	OFFICI	ER	DRIVER	OTHER
BICYLST	SEX HAIF	`	EYES	HEIGHT	WEIGH	11	BIRTHDAT	c	RACE	PRIOR MECH	ANICAL DEE	ECTS:				
OTHER	HOME PHONE				BLISINI	ESS PHON	F						NONE APPARE	NT	REFER TO NAR	RATIVE
CIREK					300111	_00 i i iON	-			VEHICLE IDEI		DESCRIBE VEHIC	CLE DAMAGE		SHADE IN DAI	MAGED AREA
OPER-	INSURANCE C	ARRIFR				POI IC	Y NUMBER			VEHICLE	TYPE			AINOD	STADE IN DAI	OLD ANLA
ATOR						i olio	· ··OMDEIX						=	MINOR		
	DIR OF TRAVE	I ON ST	REET OR H	IGHWAY	1.	ANE	THRU	TOTAL	SPD LIMIT				MAJOR F	ROLL-OVER	-	
	J SI TIMVE	_ 5.4.51	OK II				LANES	LANES	J. D LIWII	CA		DOT				
PREPAR	RED BY					Dis	0 SPATCH NOTI	0 IFIED		CAL-T REVIEWED B		TCP/PSC I	MC/MX		DATE REVIE	WED
	ID DUDLE	Y 127				_	YES	No	□ _{N/A}	DARREN		. 14			08/24/20	
'						1 1 2	7 1E9	INO	IN/A						1	

TRAFFIC CRASH REPORT CHP 555 Page 2 (Rev. 3-20) OPI 060

Page 2

0111 00010	age 2 (Nev. 3 20) Of	000																r age z
	I (MO. DAY YEAR)	TIME		NCIC #						OFFICER I.D.						IUMB		
05/25/2022		080	00	CA0570100						127						22-0	02347	
PROPERTY	OWNER					NO	NER	ADDI	RESS									
DAMAGE																		
	PERSON NOTIFIED			SAME AS OWNER	TELEPHO	ONE I	NUM	BER	MET	HOD OF NOTIFIC	CATION						LOG/INC	DIDENT NUMBER
										IN PERSON [PHON	E D	ISPA	TCH		СН	P422 22052	250040
	DESCRIPTION OF DAMAGE			•														
SEATING P	OSITION	0.00		SAF	ETY E	EQU	IPN	MEN	NT		AIR BA	\G					INATTENTIO	ON CODES
	1 TO 0 STANDARD SEATING		UPANTS ONE IN VEHICLE		9	СНП	LD F	REST	ΓRAINΤ		B - UN	KNOWN					A - CELLPHON	IE HANDHELD
	1 TO 9 - STANDARD SEATING POSITION	B - U	NKNOWN						CLE USE			BAG DE)		IE HANDSFREE IIC EQUIPMENT
122	10- REAR OCC. TRUCK/VAN	D - L.	AP BELT USED AP BELT NOT USE			S - II	N VI	EHIC	CLE USE	UNKNOWN	N - OT	HER					D - RADIO/CD	ie Equitiletti
	STATION WAGON, ETC.		HOULD HARNESS HOULDER HARNE						VEHICI	ROPER USE LE		T REQUIR		ZET	пот	E	E - SMOKING F - EATING	
4 5 6	11 - POSITION UNKNOWN	G - L	AP/SHOULDER HA AP/SHOULDER HA	ARNESS USED	D]	M/C	BIC	YCI	LE - HEI	MET		ED FRO EJECTED	IVI V	VEH	ист	Ŀ	G - CHILDREN H - ANIMALS	
'		J - P	ASSIVE RESTRAIN	NT USED	1	DRIV	/ER]	PASSEN		1 - FULI	Y EJECTI TIALLY EJ		ED			I - PERSONAL	. HYGIENE
10	0 - OTHER		ASSIVE RESTRAIN OT REQUIRED	NT NOT USED		V - N W- Y			X - NO Y - YES		3 - UNK		LCI	ED			J - READING K - OTHER	
	ITEN		RKED BELOW FO	NI LOWED BY AN	JACTEL	DICK	(*)	SHO	MII IN DI	EVDI AINED	INTHE	JADDATI	V/E					
DDIMAD		I III	KKED BELOW FO	DELOWED BY AN	ASTE			5110	OLD DI	EAILAINED	114 111121	VARKATI	V 12.			_	MOVEMENT DDE	
	/ COLLISION FACTOR R (#) OF PARTY AT FAULT	-	TRAFFIC CONT	ROL DEVICES		1	2	3	VEH	IICLE AUTOM	ATION LI	VEL	1	2	3	,	MOVEMENT PRE COLLISIO	
A CVC SECT	TION VIOLATED: CITED YES	X A	CONTROLS FU	NCTIONING			X			LEVEL - 0						Α	STOPPED	
	□ NO	-	CONTROLS NO							LEVEL - 1			X				PROCEEDING S	
B OTHER	IMPROPER DRIVING*		CONTROLS OF		·OD*	_	\dashv			LEVEL - 2				X			RAN OFF ROAD	
X C OTHER	THAN DRIVER*	ם ו	NO CONTROLS TYPE OF COLL		OR		-			LEVEL - 3				Λ			MAKING RIGHT T MAKING LEFT TI	
D UNKNO		A	HEAD-ON							LEVEL - 5							MAKING U TURN	
		В							G UNF	NOWN							BACKING	
		— —	REAR END			_	_										SLOWING/STOP	
X A CLEAR	IER (MARK 1 TO 2 ITEMS)	D	BROADSIDE HIT OBJECT				X			IICLE AUTOM AUTOMATION		NGAGED					PASSING OTHER CHANGING LAN	
B CLOUD		F				_				VER ASSISTA						_	PARKING MANE	
C RAININ	G	G	VEHICLE-PEDE	STRIAN					C PAR	RTIAL AUTOMA	ATION					L	ENTERING TRAF	FFIC
D SNOWI		X H	OTHER VEHI	CLE V BICYCLI	Е					NDITIONAL AU		NC					OTHER UNSAFE	
F OTHER			MOTOR VEHICL	E INVOLVED W						H AUTOMATIC							XING INTO OPPO	OSING LANE
F OTHER G WIND	<u> </u>	Α	NON-COLLISIO	.E INVOLVED WI'	IH	\dashv	\dashv			L AUTOMATIC (NOWN	JIN		_			_	PARKED MERGING	
LIGHTIN	NG		PEDESTRIAN						• 0.1.								TRAVELING WR	ONG WAY
X A DAYLIG		С	OTHER MOTOR	R VEHICLE						ER ASSOCIAT		ORS				R	OTHER*	
B DUSK -		D		LE ON OTHER RE	YAWC	1	2	3	,	ARK 1 TO 2 IT	-,	_					LANE SPLITTING	
	STREET LIGHTS NO STREET LIGHTS	E	PARKED MOTO	OR VEHICLE					A CVC S	SECTION VIOLATED:	CITED	YES NO	1	2	3	SC	DBRIETY - DRUG MARK ALL TH.	
	STREET LIGHTS NOT	_	BICYCLE				П		B cvc s	SECTION VIOLATED:	CITED	YES		X		Α	HAD NOT BEEN	
FUNCT	TIONING	Н	ANIMAL:									NO					HBD - UNDER IN	
	VAY SURFACE								C cvc s	SECTION VIOLATED:	CITED	YES				-	HBD - NOT UNDI	
X A DRY B WET			FIXED OBJECT	:	ŀ				D			NO					HBD - IMPAIRME UNDER DRUG IN	
C SNOW	Y - ICY	J	OTHER OBJEC	T:						ON OBSCURE	MENT:					_	DRE EXAM CON	
	ERY (MUDDY, OILY, ETC.)									TTENTION*							STIMULANT	
ROADV	WAY CONDITIONS	к	ADDITIONAL O	BJECT(S) STRUC	K					P & GO TRAF							HALLUCINOGE	EN
	K 1 TO 2 ITEMS)	v I.	PEDESTRIAN A			\dashv	\dashv			ERING /LEAV		Р	_					E ANESTHETICS
	, DEEP RUT* MATERIAL ON RDWAY*		NO PEDESTRIA			\dashv	+			VIOUS COLLI FAMILIAR WITI			_				NARCOTIC AN INHALANT	IALGESIC
	UCTION ON ROADWAY*	"	AT INTERSECT		ŀ	\dashv	+			ECTIVE VEH		CITED					CANNABIS	
	RUCTION - REPAIR ZONE	С	CROSSING IN		тс			ľ			Γ	YES					DEPRESSANT	-
 	CED ROADWAY WIDTH	$\sqcup \bot$	IN INTERSECTI			\perp						NO					IMPAIRMENT - P	
F FLOOD		-	CROSSING - NO IN ROAD - INCL			\dashv	-			NVOLVED VE	HICLE		X			_	IMPAIRMENT NO NOT APPLICABL	
G OTHER	USUAL CONDITIONS		NOT IN ROAD	ODES SHOULDE	.15	X	X		M OTH	IEK" NE APPARENT	Г						SLEEPY/FATIGU	
11 110 011	000/12 00/12/11/01/0		APPROACHING	LEAVING SCH B	BUS					NAWAY VEHIC								
SKETCH	<u> </u>					MIS	CEL	LAI	NEOUS								SPECIAL INFOR	
																	HAZARDOUS MA	
				INDICATE NO	RTH												CELL PHONE HA CELL PHONE HA	
																-	USE	
														X		D	CELL PHONE NO	OT IN USE
													X				CELL PHONE US	
																	SCHOOL BUS RE	
													_				BIKEWAY FACIL SHARED ROADV	
																	CLASS I - BIKE P	
													X	X			CLASS II - BIKE L	
																	CLASS III - BIKE	
																	CLASS IV - SEPA BIKEWAY	ARATED

INJURED/WITNESSES/PASSENGERS CHP 555 Page 3 (Rev. 3-20) OPI 060

	Pa	ge 3	
AIR BAG	SAFETY EQUIP.	EJECTED	
P	W	1	
PHON	1E		
NOTIF	FIED		
PHON	ie.		
PHON	NE.		
NOTIF	FIED		
NOTIF	FIED		

05/25/20	LLISION (MO. DAY	(YEAR)		TIME (2400 0800)	CA0570100)	OFFICE 127	R I.D.					NUMBE 22-0		7		
					EVTENT OF IN				IIIDED W	/A C //	VI ONE	٠,		22 0.		,		
WITNESS ONLY	PASSENGER ONLY	AGE	SEX	FATAL	SUSPECTED SERIOUS	SUSPECTED MINO	OR POSSIBLE	DRIVER	PASS. PE		YCLIST		OPER	PARTY NUMBE			SAFETY EQUIP.	EJECTED
				INJURY	INJURY	INJURY	INJURY			1	X			1	1	P	W	1
NAME/D.O.B./	/ADDRESS														١.	TELEPHO	NE	
(IN JURED ON	ILY) TRANSPORT	ED BV			EMS RUN NUI	ADED.			TAL	EN TO								
AMR	ILI) IRANGFORI	ED 61			EM3 KUN NUI	WIDER					VIS M	ED CI	ENTI	ER				
DESCRIBE IN UNKNO		NG FO	R SAC	COUNT	ΓY CORONER ΤΟ	O CONFIRM I	NJURIES											
													/ICTIM	OF VIOLE	NT CF	RIME NOTI	FIED	
X #1										1								
NAME/D.O.B.	/ADDRESS														Ι.	TELEPHO	NE	
																(C)		
(INJURED ON	ILY) TRANSPORT	ED BY			EMS RUN NUI	MBER			TAR	EN TO								
DESCRIBE IN	IJURIES																	
										7			/ICTIM	OF VIOLE	NT CF	RIME NOTI	FIED	
NAME/D.O.B./	(ADDRESS												ELEPH	IONE				
TATANE D.O.D.	NDBREGO												LLLII	IONE				
(INJURED ON	ILY) TRANSPORT	ED BY			EMS RUN NUI	MBER			TAF	EN TO								
DESCRIBE IN	JURIES																	
													/ICTIM	OF VIOLE	NT OF	NAE NOT	EIED	
													71011111	T	T	CIIVIL INOTI	T	
NAME/D.O.B./	/ADDRESS											Т	ELEPH	IONE				
(INJURED ON	ILY) TRANSPORT	ED BY			EMS RUN NUI	MBER			TAP	EN TO								
DESCRIBE IN	JURIES																	
												<u>'</u>	/ICTIM	OF VIOLE	NT CF	RIME NOTI	FIED	
]								
NAME/D.O.B.	/ADDRESS		'		,							Ť	ELEPH	IONE				
(INJURED ON	ILY) TRANSPORT	ED BY			EMS RUN NUI	MBER			TAF	EN TO								
DECODINE IN																		
DESCRIBE IN	JURIES																	
												\	/ICTIM	OF VIOLE	NT CF	RIME NOTI	FIED	
NAME/D.O.B./	/ADDRESS											Т	ELEPH	IONE				
(INJURED ON	ILY) TRANSPORT	ED BY			EMS RUN NUI	MBER			TAH	EN TO								
DESCRIBE IN	JURIES																	
													/ICTIM	OF VIOLE	NT CF			
NAME OF PRI	EPARER DUDLEY				I.D. NUMBER 127		O. DAY YEA 05/25/2022	R	NAME OF I								o. day 08/24/20	
ועוויזים					121				- min	ا 1 ، د.								,

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCU 05/25/2022	JRENCE	TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER	NUMBER 22-02347	
"X" ONE			TYPE SUPPLEMENTAL ("X" API		22-023-1	
✓ Narrative ✓ Collision Report		BA update	Fatal	Hit and run update		
Supplement Other:			Hazardous Materials	School bus	Other:	
CITY/COUNTY/JUDICIAL D DAVIS/YOLO/YOLO		URT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR/DA	AIRY RD				STATE HIGHWAY RELATED Yes V No	

FACTS:

NOTIFICATION:

On May 25, 2022, I was working in a full police uniform as a training officer for new Davis Police Officers. Davis Police Officer Xia Vang was doubled with me at the time as a trainee. My regular assignment is working traffic enforcement and I am generally assigned to work on a marked police motorcycle. My typical duties include issuing traffic related citations to motorists, bicyclists and pedestrians. I am also regularly assigned to investigate traffic collisions. My specific training related to traffic collision investigation includes:

- POST Basic Academy LD 28 Traffic Collision Investigation 2005
- POST Traffic Collision Investigation, Intermediate May 2016

At approximately 0920 hours I was asked by Davis Police Department Sergeant Dias to assist the University California Davis Police Department (UCDPD) with a major injury collision that occurred at the intersection of Hutchinson Drive and Dairy Road, which is located on the University California Davis (UC Davis) campus. Sergeant Dias stated the collision involved a garbage truck and a bicycle. Sergeant Dias stated UCDPD would be handling the report, but requested someone with traffic collision investigation experience respond to assist. I responded to the scene from the Davis Police Department and arrived at 0944 hours.

All times, speeds, and measurements are approximate. I obtained the measurements using a 100 foot tape measure.

SCENE DESCRIPTION:

Hutchinson Dr. is a four lane roadway with two lanes for eastbound traffic and two lanes for westbound traffic. East and westbound Hutchinson Dr. is divided by solid double yellow lines. Marked bicycle lanes and raised concrete sidewalks are on the north and south side of Hutchinson Dr.

At the intersection of Hutchinson Dr. and Dairy Rd. the number one eastbound lane of Hutchinson Dr. turns into a mandatory left turn lane to go into the Pavilion parking structure. The number two eastbound lane of Hutchinson Dr. has white arrow markings painted on the ground indicating you can either proceed straight or make a right turn to go south on Dairy Rd.

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

MANNATIVE/SOLI ELIMENTAL		
CHP 556 (Rev. 7-90) OPI 042		

DATE OF INCIDENT/OCCU 05/25/2022	JRENCE	TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER 127	NUMBER 22-02347	
"X" ONE "X" ONE			TYPE SUPPLEMENTAL ("X" AP BA update Hazardous Materials	PLICABLE) Fatal School bus	Hit and run update Other:	
CITY/COUNTY/JUDICIAL E DAVIS/YOLO/YOLO		URT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR/DA	AIRY RD				STATE HIGHWAY RELATED Yes Ý No	

Dairy Rd. is a two-lane roadway with one lane for northbound traffic and one lane for southbound traffic. The roadway is divided by solid double yellow lines. There is also a marked bicycle lane, and a raised concrete sidewalk to the east and west side.

When I arrived on scene I observed the intersection of Hutchinson Dr. and Dairy Rd. closed off by crime scene tape. I noticed Dairy Rd. was completely closed to through vehicle, pedestrian, and bicycle traffic. In the middle of the road on Dairy Rd., approximately 30 feet south of Hutchinson Dr., was a debris field consisting of clothing, shoes, bicycle helmet and tarot cards.

Parties:

<u>Party #1 (B1, </u>) - I was told the involved bicyclist, later identified as	, had been
transported by AMR unit 313 to UC Davis Medical Center. B1	was
pronounced deceased at 0933 hours.	

Vehicle #1 (V1, Electric Bicycle)

Party #2 (D2, D2). The driver of the garbage truck (V2), was identified by a valid California Driver's license as Detective E. Schneider. I was standing by as Detective Schneider was speaking with D2 about consenting to a blood draw. D2 told Detective Schneider he would consent to the blood draw. Detective Schneider drove D2 to have the blood draw done. Detective Schneider told me he would take possession of the blood sample and book it into evidence at UCDPD. Although a blood sample was taken, there was no indication that was impaired or under the influence of alcohol and/or drugs.

<u>Vehicle #2 (V2, UC Davis Garbage Truck)</u> was located approximately 40 feet south of the debris field stopped in the southbound lane of Dairy Rd. The vehicle was parked at an angle facing a southwest direction.

V2 was driven by a UC Davis employee to the UC Davis Fleet. At Fleet they parked it inside a service bay. They allowed us access to an underground walkway so we could inspect the undercarriage of V2. Davis Police Public Safety Specialist Schwend took photos of V2. After we inspected V2, I asked that V2 be parked in a secured area and taken out of the fleet. I did this because a class A license is required to drive V2 and UC Davis Fleet is a secured area that can accommodate a large truck.

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCURENCE TIME (2 05/25/2022 0800		TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER 127	NUMBER 22-02347		
"X" ONE Y Narrative Supplement "X" ONE Y Collision Report Other:			TYPE SUPPLEMENTAL ("X" AP BA update Hazardous Materials	PLICABLE) Fatal School bus	Hit and run update Other:		
CITY/COUNTY/JUDICIAL DISTRICT DAVIS/YOLO/YOLO SUPERIOR COURT REPORTING DISTRICT/BEAT CITATION NUMBER UCD							
LOCATION/SUBJECT HUTCHISON DR/DA	AIRY RD				STATE HIGHWAY RELATED Yes No		

PHYSICAL EVIDENCE:

- Pieces of white reflector located on Dairy Rd just south of Hutchinson Dr.
- Scrape marks were found in the south bound lane of Dairy Rd.
- Clothing fiber from B1 was found in the south bound lane of Dairy Rd.
- Bicycle helmet from B1 located in the south bound lane of Dairy Rd.
- Personal property of B1 located in the southbound lane of Dairy Rd.

Refer to Rough Sketch and Factual Diagram for further.

VIDEO EVIDENCE:

While at the scene for this traffic collision, I noticed the UC Davis Health Clinic was on the corner of Hutchinson Dr. and Dairy Rd. I also noticed there was a security camera on the southwest corner of the building and another camera on the northeast corner of the building. I was later informed by UCDPD that the traffic collision was captured on the two cameras. On May 26, 2022, I was given a thumb drive by UCDPD Detective E. Lee that contained the security video from the Health Clinic.

I watched the camera angle from the north west corner of the building it depicts the following:

The camera date stamped was May 25, 2022 at 8:06 hours. It shows a white SUV in the number one position in the #2 lane of east bound Hutchinson. A Grey SUV in the number one lane. There are no bicyclists in the east bound lane of Hutchinson.

8:06:07 Witness vehicle comes into camera view and is north bound Dairy Rd. in the number 1 position at the limit line.

8:06:10 Garbage truck comes into camera view and is driving east bound Hutchinson Dr.

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

CHD	56 (Pa	/ 7-QO)	ODI 0/12

PREPARER'S NAME AND I.D. NUMBER

CHP 556 (Rev. 7-90)	OPI 042					Page 7
DATE OF INCIDENT/OCCU	JRENCE	TIME (2400)	NCIC NUMBER	OFFICER I.D. NUMBER	NUMBER	
05/25/2022 "X" ONE	"X" ONE	0800	CA0570100	127	22-02347	
Narrative	Collision Rep	ort	TYPE SUPPLEMENTAL ("X" BA update	· · Fatal	Hit and run update	
Supplement	Other:	on .	Hazardous Materials	School bus	Other:	
CITY/COUNTY/JUDICIAL E DAVIS/YOLO/YOLO		OURT	Tiazarada materiale		REPORTING DISTRICT/BEA	T CITATION NUMBER
LOCATION/SUBJECT					STATE HIGHWAY RELATED)
HUTCHISON DR/DA	AIRY RD				·· Yes Ý	No
8:06:18 8:06:19 8:06:28 8:06:29	ite SUV and B Garbage to Bicyclist et B Bicyclist row White SU I Garbage to B SUV and	d slows dow ruck comes enters camera next to vehic V begins to	ing and makes a left in. The garbage tructo a stop. a view and is riding le that is directly be move east on Hutch to move. Bicyclist is	k has the right turn east on Hutchinsor hind garbage truck. iinson Dr.	signal activated.	
8:06:33	3 Garbage t	ruck starts to	o make right turn. B	sicyclist crosses the	white solid limit lin	ne.
	_	ruck and bic ne passenger	yclist collide. Point side.	of impact appears t	o be on the corner	of the
8:06:35	5 Garbage t	ruck is facin	g south on Dairy Ro	l. has not complete	d turn.	
8:06:37	7 Garbage t	ruck comple	tes turn and is now	south on Dairy RD		
8:06:39	9					
8:06:40						
8:06:40	0:405					
8:06:42	1			Garbage	truck is out of came	era view.
I then watched	the second	camera ang	le which covers nor	th and south bound	Dairy Rd and also	the

DAVID DUDLEY 127 Use previous editions until depleted.

Date:

05/25/2022

90 57841

DATE

08/24/2022

REVIEWER'S NAME

DARREN PYTEL

NAKKAI	IVE	/SUF	'PLE	MEN	IΑ

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCU 05/25/2022	(11,		NCIC NUMBER CA0570100	OFFICER I.D. NUMBER	NUMBER 22-02347	
"X" ONE Narrative Supplement	"X" ONE Solition Report Other:	Collision Report BA		PLICABLE) Fatal School bus	Hit and run update Other:	
CITY/COUNTY/JUDICIAL DAVIS/YOLO/YOLO		URT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR/DA	AIRY RD				STATE HIGHWAY RELATED Yes Ý No	

intersection of Hutchinson Dr. and Dairy Rd.

I started the footage at 08:06:00 It shows a white SUV in the number one position in the #2 lane of east bound Hutchinson. A Grey SUV in the number one lane. There are no bicyclists in the east bound lane of Hutchinson.

8:06:03 Witness vehicle enters the screen north bound on Dairy Rd.

8:06:10 Garbage Truck (V2) is seen east bound on Hutchinson Dr. by the soccer fields.

8:06:18 Garbage truck stops behind a White SUV.

8:06:23 Bicyclist (B1) appears in camera view and is east bound Hutchinson Dr. passing by the soccer fields.

8:06:29 Garbage truck begins to move. Bicyclist is at the passenger side rear tires.

8:06:34 Bicycle is now at Garbage truck's passenger side door as truck starts to make right turn.

8:06:34:199 Front passenger tire of Garbage truck is turned to the right. Bicyclist is in front of the tire, and by the front bumper.

8:06:34:533 Garbage truck and Bicyclist collide.

8:06:35 Garbage truck is facing south on Dairy Rd. has not completed turn.

8:06:37 Garbage truck completes turn and is now south on Dairy RD.

8:06:40

8:06:40:405

PREPARER'S NAME AND I.D. NUMBER Date: REVIEWER'S NAME DATE DAVID DUDLEY 127 05/25/2022 DARREN PYTEL 08/24/2022

Use previous editions until depleted.

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCI 05/25/2022	JRENCE	TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER 127	NUMBER 22-02347	
"X" ONE Supplement	"X" ONE Solition Report Other:	ort	TYPE SUPPLEMENTAL ("X" AP BA update Hazardous Materials	PLICABLE) Fatal School bus	Hit and run update Other:	
CITY/COUNTY/JUDICIAL I		URT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR/DA	AIRY RD				STATE HIGHWAY RELATED Yes No	

8:06:41 Garbage truck starts to pull to the right side of the roadway.

8:06:47 Garbage truck comes to a stop.

8:06:56 Driver (D2) exits the Garbage truck.

8:07 Driver (D2) runs over to B1 and makes contact.

STATEMENTS:

Party-2 (

While I was standing by with UCDPD Detective Schneider, UCDPD Sergeant R. Fenn approached me and informed me that I would be taking over this investigation. I activated my body worn camera and asked D2 to provide me a statement. D2 provided me the following statement.

"I was traveling eastbound here on Hutchinson Drive. I came to a stop with the red light. It was a red light making a right hand turn. There was a vehicle parked here (D2 was pointing to the northbound lane of Dairy Road). Right now with all this right now, I don't know if it was still a red light or if and it turned green at the time. I proceeded to make a right-hand turn and never once saw the bicyclist on the right-hand side of the truck. This is a common turn that I take it three times a week going to my next location. So it's not uncommon for us to kinda hit that curb there on the corner (D2 pointed to the southwest corner of Hutchinson Dr. and Dairy Rd.). With that being said, my passenger side steps of the truck are a little loose so you kinda hear a wobble. I made the right-hand turn, I heard the wobble (which D2 stated was the passenger side steps) proceeded thought it was just a normal curb so I looked in the mirror. As I looked in the mirror I saw a shoe down on the ground, so I pulled over immediately and hopped out, and there was a pedestrian down or a bicyclist I should say."

After getting D2's preliminary statement I asked some clarifying questions. D2 stated as he was eastbound on Hutchinson Dr. he came up to a stale red light (stale meaning the light had already been red for some period of time). He stated he was the first vehicle at the limit line, and as he approached the intersection there were no bicyclists in the bike lane. He was in the lane that you can either go straight (eastbound Hutchinson Dr.) or make a right turn to go southbound on Dairy Rd. He stated the bike lane was to his immediate right. He could not remember if the vehicle traffic for westbound Hutchinson Dr was moving. He also stated there were no bicyclists or pedestrians crossing anywhere during this time.

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

DAVID DUDLEY 127

CHP 556 (Rev. 7-		IIAL				Page 10
DATE OF INCIDENT/O 05/25/2022	CCURENCE	TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER	NUMBER 22-02347	
"X" ONE Narrative Supplement	"X" ONE Collision R Other:	teport	TYPE SUPPLEMENTAL ("X" BA update Hazardous Materials	APPLICABLE) Fatal School bus	Hit and run update Other:	
CITY/COUNTY/JUDICI. DAVIS/YOLO/YO		COURT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR	DAIRY RD				STATE HIGHWAY RELATED Yes ý I	No
Witness #1 (25, 2022, at W1 was nor waiting to mon Hutchinson bicyclist werbike lane. W garbage truck Hutchinson W1 stated as stated there stated the bicyclist was Witness #2 (who UCDPI	2022 at appllow up que give his attor was record was record was record was a gard at though was a gard stated both was a right bor. when both was another cyclist was it is saying. W1	proximately 14 stions. The provided on my body and provided on the part of the garbage truck (The garbage truck made of the garbage truck made o	act info and we can all worn camera). given a phone number Davis Police Department the following state of the red light hinson Dr. W1 states (Y2) and a bicyclist (ruck was stopped in truck and the bicyclid not know what come truck and bicyclist the right turn, it collists	arrange a conference of a witness by ment I called the watement over the part. W1 was right at 1 to his left (which B1). W1 stated bothe lane and the bis ist started to move olor the traffic sign started to move. Ided with the bicyclass able to speak. Wand called 911.	a UCDPD officer. Of the same time and was would be eastbound the garbage truck cyclist was stopped at the same time, and was for eastbound the same time, and was for eastbound the cyclist. It is if he could help held to could not recall was standing in the cyclist and was standing in the cyclist.	d to ask ne (this On May tiffied as as a traffic and the in the nd the d W1 ner. W1 what the
		•	I have been unable to	-		0
PREPARER'S NAME A	ND I.D. NUMBER		Date:	REVIEWER'S NAME		DATE

DARREN PYTEL

05/25/2022

08/24/2022

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCU	TE OF INCIDENT/OCCURENCE TIME (2400)		NCIC NUMBER	OFFICER I.D. NUMBER	NUMBER	
05/25/2022		0800	CA0570100	127	22-02347	
"X" ONE "X" ONE		TYPE SUPPLEMENTAL ("X" API	TYPE SUPPLEMENTAL ("X" APPLICABLE)			
V Narrative	Collision Repo	rt	BA update	· · Fatal	Hit and run update	
Supplement	Other:		Hazardous Materials	School bus	Other:	
CITY/COUNTY/JUDICIAL D	DISTRICT				REPORTING DISTRICT/BEAT	CITATION NUMBER
DAVIS/YOLO/YOLO	SUPERIOR CO	URT			UCD	
LOCATION/SUBJECT					STATE HIGHWAY RELATED	
HUTCHISON DR/DA	AIRY RD				·· Yes \bigvee No	

OPINIONS AND CONCLUSIONS:

SUMMARY:

Both B1 and D2 were traveling eastbound on Hutchinson Dr. prior to the collision. B1 was lawfully traveling in the marked bicycle lane (although she was on an electric bike, that particular bicycle is allowed to lawfully travel in the bicycle lane). D2 intended to make a right turn to southbound Dairy Rd. From approximately two car-lengths back, V2 had moved into a position that was as far right as practicable based on the length and width of the large vehicle (garbage truck) to make the right turn to Dairy Rd.

Sections 22100, 21717, and 21209 of the Vehicle Code govern right turns at intersections where bicycle lanes are involved.

- 22100. Except as provided in Section 22100.5 or 22101, the driver of any vehicle intending to turn upon a highway shall do so as follows:
 - (a) Right Turns. Both the approach for a right-hand turn and a right-hand turn shall be made as close as practicable to the right-hand curb or edge of the roadway except:
 - (1) Upon a highway having three marked lanes for traffic moving in one direction that terminates at an intersecting highway accommodating traffic in both directions, the driver of a vehicle in the middle lane may turn right into any lane lawfully available to traffic moving in that direction upon the roadway being entered.
 - (2) If a right-hand turn is made from a one-way highway at an intersection, a driver shall approach the turn as provided in this subdivision and shall complete the turn in any lane lawfully available to traffic moving in that direction upon the roadway being entered.
 - (3) Upon a highway having an additional lane or lanes marked for a right turn by appropriate signs or markings, the driver of a vehicle may turn right from any lane designated and marked for that turning movement.
- 21717. Whenever it is necessary for the driver of a motor vehicle to cross a bicycle lane that is adjacent to his lane of travel to make a turn, the driver shall drive the motor vehicle into the

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

90 57841

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCU 05/25/2022	JRENCE	TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER 127	NUMBER 22-02347	
"X" ONE Supplement	"X" ONE Solition Report Other:	ort	TYPE SUPPLEMENTAL ("X" AP BA update Hazardous Materials	PLICABLE) Fatal School bus	Hit and run update Other:	
CITY/COUNTY/JUDICIAL E DAVIS/YOLO/YOLO		URT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR/DA	AIRY RD				STATE HIGHWAY RELATED Yes Ý No	

bicycle lane prior to making the turn and shall make the turn pursuant to Section 22100.

- 21209.(a) No person shall drive a motor vehicle in a bicycle lane established on a roadway pursuant to Section 21207 except as follows:
 - (1) To park where parking is permitted.
 - (2) To enter or leave the roadway.
 - (3) To prepare for a turn within a distance of 200 feet from the intersection.
- (b) This section does not prohibit the use of a motorized bicycle in a bicycle lane, pursuant to Section 21207.5, at a speed no greater than is reasonable or prudent, having due regard for visibility, traffic conditions, and the condition of the roadway surface of the bicycle lane, and in a manner which does not endanger the safety of bicyclists.

Section 21208 of the Vehicle Code governs the movement of bicycles in a bike lane.

21208

- (a) Whenever a bicycle lane has been established on a roadway pursuant to Section 21207, any person operating a bicycle upon the roadway at a speed less than the normal speed of traffic moving in the same direction at that time shall ride within the bicycle lane, except that the person may move out of the lane under any of the following situations:
 - (1) When overtaking and passing another bicycle, vehicle, or pedestrian within the lane or about to enter the lane if the overtaking and passing cannot be done safely within the lane.
 - (2) When preparing for a left turn at an intersection or into a private road or driveway.
 - (3) When reasonably necessary to leave the bicycle lane to avoid debris or other hazardous conditions.
 - (4) When approaching a place where a right turn is authorized.
- (b) No person operating a bicycle shall leave a bicycle lane until the movement can be made with reasonable safety and then only after giving an appropriate signal in the manner provided in Chapter 6 (commencing with Section 22100) in the event that any vehicle may be affected by the movement.

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

Use previous editions until depleted.

NARRATIVE/SUPPLEMENTA

CHP 556 (Rev. 7-90) OPI 042

DATE OF INCIDENT/OCCURENCE TIME (2400) 05/25/2022 0800		` ,	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER 127	NUMBER 22-02347	
"X" ONE Y Narrative Supplement "X" ONE Y Collision Report Other:		TYPE SUPPLEMENTAL ("X" AP BA update Hazardous Materials	PLICABLE) Fatal School bus	Hit and run update Other:		
CITY/COUNTY/JUDICIAL DISTRICT DAVIS/YOLO/YOLO SUPERIOR COURT					REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT HUTCHISON DR/DAIRY RD					STATE HIGHWAY RELATED Yes You	

Here, although D2 did not move the truck into the bike lane, he did position it as far right as reasonably practicable in the roadway in order to set up his right turn to southbound Dairy Rd. Based on the size and width of V2, had V2 occupied the bicycle lane, as a passenger vehicle is required to do (and can do), V2 would have driven over the southbound curb of Hutchinson Dr. driving on the sidewalk and potentially colliding with the pedestrian push button and the traffic signal pole or would have had to turn using the entirety of the northbound Dairy Rd. travel lane, which was then occupied by a vehicle. D2 stated he makes this turn three times a week because it is part of his route. He mentioned he had hit the curb on prior occasions, but this makes sense because of the size of the vehicle in relation to the tight turning radii for that corner. In short, D2 set up to make the right turn, staying in the through traffic lane, as was reasonably practicable so he would not strike the inside curb with V2's passenger side rear tires.

V2 had come to a complete stop for the red light. V2's right turn signal was activated as V2 approached the intersection and remained activated while stopped for the red traffic signal. This turn signal is visible from the front and the rear of V2. Along the passenger side the turn signal protrudes out from the vehicle and has an orange lens to the front and rear.

B1 approached V2 as V2 was beginning to move once the eastbound Hutchinson Dr traffic signal turned green. It would be reasonable for D2 to be looking forward, as his vehicle was also moving forward, to make sure the vehicle in front of him cleared the intersection.

Since V2 was a large commercial vehicle and could not occupy the bicycle lane, B1 continued to ride in the bicycle lane, attempting to overtake V2 and ultimately collided with V2 as it made a right turn onto Dairy Rd. B1 was lawfully traveling in the bicycle lane and it does not appear, based on her riding behavior as observed in the video of the incident, she saw that V2 was going to make a right turn as indicated by the active turn indicator. Additionally, because B1 was riding an electric bicycle she was traveling at a speed greater than a bicyclist likely would have while on the right side of the garbage truck. From a reasonable perspective, this would have made it less likely that D2 would have seen her because as V2 began to make the right hand turn onto Dairy Rd. a reasonable driver would be looking in front of their vehicle, and making sure there was enough clearance from any vehicle stopped on Dairy Rd to complete his right turn. It is reasonable to believe that with D2 looking in front of him and also looking to where he was turning, he could not also continually check his mirrors to see if a bicyclist was right next to him.

I did a Google Search for the dimensions of a Jetson Bolt Pro bicycle, the same bicycle B1 was riding. Per Jetson's website, it shows the dimensions of the bike are 46.85(L) 24.02 (W) 9.06 (H). Using a

<u> </u>			
PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

Use previous editions until depleted

INCINIC	114 1730		
CHP 556 ((Rev. 7-90)	OPI 042	

DATE OF INCIDENT/OCCURENCE TIME (2400 05/25/2022 0800		TIME (2400) 0800	NCIC NUMBER CA0570100	OFFICER I.D. NUMBER 127	NUMBER 22-02347	
"X" ONE y Narrative Supplement "X" ONE y Collision Report Other:		TYPE SUPPLEMENTAL ("X" AP BA update Hazardous Materials	PLICABLE) Fatal School bus	Hit and run update Other:		
CITY/COUNTY/JUDICIAL DISTRICT DAVIS/YOLO/YOLO SUPERIOR COURT				REPORTING DISTRICT/BEAT UCD	CITATION NUMBER	
LOCATION/SUBJECT HUTCHISON DR/DAIRY RD					STATE HIGHWAY RELATED Yes No	1

measuring tape I measured the handle bar height of the bicycle. It was approximately 38" from the ground to the top. I then measured the seat, which was approximately 37" from the ground to the top of the seat.

While I was still on scene Officer Vang and I were able to has a listed height of 5'-4" on a CA ID Card. I asked Officer Vang how tall he was. He stated he is 5'-6". I had Officer Vang place the bicycle next to the passenger side door of V2. From my position in the driver's seat of V2 I was unable to see Officer Vang using the double set of mirrors on the passenger side of V2 (it should be noted I did not move the seat once I got in. The seat remained in the same distance from steering wheel as D2 had it). Additionally, I also could not see Officer Vang through the passenger side window. Officer Vang, while doing this, was on the sidewalk which is approximately 4" higher than the roadway. Officer Vang was on the sidewalk due to the final positioning of V2 in the roadway. Based on where B1 was at in relation to the blind spots on V2, and also the height of the bicycle B1 was riding it is likely D2 never saw B1 next to his vehicle.

AREA OF IMPACT:

AOI was determined by evidence on at the scene. AOI was approximately 2 feet 5 inches north of the south curb line prolongation of Hutchinson Dr. and approximately 2 feet 6 inches east of the west curb line prolongation of Dairy Rd.

CAUSE:

Here, a confluence of events were factors in this collision. The large size of the garbage truck in relation to the corner radii made it impractical for the driver to make a right turn from the bicycle lane which would have clearly signaled to other traffic he was make a right turn. B1 was riding an electric bicycle, which appeared to be traveling at a speed greater than a normal bicycle would. This ended up placing B1 directly in the path of the turning truck. The large size of the truck also made it difficult for D2 to see everything that was occurring on the right side of the vehicle prior to the impact, including B1 which was traveling to the right at a speed greater than his. Lastly, it does not appear that B1 saw that D2 was going to make a right turn based on the activated turn indicator. All of these factors make it difficult to determine the exact vehicle code violation that was the primary collision factor.

Due to the aforementioned, the cause of this collision is "other than driver." (See California Highway

PREPARER'S NAME AND I.D. NUMBER	Date:	REVIEWER'S NAME	DATE
DAVID DUDLEY 127	05/25/2022	DARREN PYTEL	08/24/2022

Use previous editions until depleted.

NARRATIVE/SUPPLEMENTAL

CHP 556 (Rev. 7-90)	OPI 042					Page 15
DATE OF INCIDENT/OCCU	JRENCE	TIME (2400)	NCIC NUMBER	OFFICER I.D. NUMBER	NUMBER	
05/25/2022	"V" ONE	0800	CA0570100	127	22-02347	
'X" ONE Narrative	"X" ONE Collision Repo	ort	TYPE SUPPLEMENTAL (". BA update	X" APPLICABLE) Fatal	Hit and run update	
y Narrative Supplement	Other:		Hazardous Materials		Other:	
CITY/COUNTY/JUDICIAL I		URT			REPORTING DISTRICT/BEAT UCD	CITATION NUMBER
LOCATION/SUBJECT					STATE HIGHWAY RELATED	
HUTCHISON DR/DA	AIRY RD				·· Yes Ý N	lo
Patrol Collisio RECOMMEN Due to the nat for review.	NDATIONS	<u>S:</u>		ppy to the Yolo Cour	nty District Attorney	's office
PREPARER'S NAME AND	I.D. NUMBER		Date:	REVIEWER'S NAME		DATE
DAVID DUDLEY 12			05/25/2022	DARREN PYTEL		08/24/2022

Use previous editions until depleted.

Page 1 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 1 - Supplement - Scene Entry Log

1 **Supplement:** 2 3 On 5/25/2022 at approx. 0925 hours, Ofc. Dudley and I were dispatched to assist UC Davis PD with a fatal TC 4 involving a vehicle versus bicyclist that occurred near the intersection of Hutchison Dr. and Dairy Rd. 5 6 At approx. 0944 hours, Ofc. Dudley and I arrived on scene. The scene of the accident had already been cordoned 7 off by UCD PD Officers but a crime scene entry log had not yet been established. 8 9 At approx. 0950 hours, I started a crime scene entry log (see attached). The times logged for entry and exit of the 10 accident were approximations. The below individuals entered/exited the scene and were logged. 11 12 West Sacramento PD - Andrea Barnett (Drone operations) 13 West Sacramento PD - Elaine Carlton (Drone operations) 14 15 At approx. 1334 hours, the scene of the accident was cleaned up, cleared, and opened back up to the public. 16 17 Disposition: 18 19 Attach to main case 20 21 22 23 24

Page 1 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 2 - Roadway Measurements and Debris measurement in roadway

1 2 3

The roadway dimensions for the east bound lanes of traffic for Hutchinson Dr. are:

The roadway width is approximately 27 feet 9 inches. The bike lane is approximately 6 feet 11 inches. The number two lane is approximately 10 feet 4 inches. The number one lane is approximately 9 feet 4 inches.

4 5 6

7

8

The roadway dimensions for north and south bound Dairy Rd are: The total roadway width is 34 feet 2.75 inches. The bike lane for south bound Dairy Rd is 5 feet 9.5 inches. The south bound lane is 10 feet 2 inches. Double yellow lines approximately 8.75 inches separate the north and south bound lanes. The north bound lane is 10 feet 1.5 inches and the north bound bike lane is 6 feet.

9 10 11

12

DEBRIS IN ROADWAY MEASUREMENTS:

13 14 feet east of the west curb line prolongation of Dairy Rd.

Bicycle peddle scrape: 1 feet 9 inches south of the south curb line prolongation of Hutchinson Dr. and 4

15 16 • White bicycle reflector: 7 feet 1 inch south of the south curb line prolongation of Hutchinson Dr. and 6 feet east of the west curb line prolongation of Dairy Rd.

17 18

Blue clothing fiber: 25 feet 10.5 inches south of the south curb line prolongation of Hutchinson Dr. and 12 feet 6 inches east of the west curb of Dairy Rd.

19 20 21

• Bicycle scrape: 28 feet 10 inches south of the south curb line prolongation of Hutchinson Dr. and 11 feet 1 inch east of the west curb of Dairy Rd.

222324

25

262728

30 31

29

 Bicycle Helmet: 33 feet 6 inches south of the south curb line prolongation of Hutchinson Dr. and 18 feet east of the west curb of Dairy Rd.

323334

35

36

DISPOSITION:

Attach to main report

37 38

39

40

Prepared By:
127 DUDLEY, DAVID
[] BODY CAMERA RECORDED

Date: 05/26/2022

Approved By: 14 PYTEL, DARREN

Date: 08/24/2022

Page 1 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 3 - BWC VIDEO FROM UCDPD - 05/27/2022 - INC #2205270086

FRIDAY
 05/27/2022
 1500 HOURS

4 5

6

7

SUPPLEMENT:

On the above date and time, I received an envelope containing (1) USB flash drive and (3) CD's containing bodyworn camera footage from UC Davis Police Department Patrol Officers Fenn #1014, Grande #1041, and Rodriguez #1028 for this incident.

8 9

The flash drive and CDs were provided to DPD Property Specialist Luiz for booking into evidence for this case (*Item #18*).

12

13 **Disposition:**

14 Attach to main case.

Prepared By:		Date:	Approved By:		Date:	
	231	ADAMS, AUSTIN	05/27/2022	14	PYTEL, DARREN	08/24/2022
	I I RODY	CAMERA RECORDED	LLCAR CAMERA RECORDED			

Page 1 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 4 - Security Camera Video from 684 Hutchinson Dr.

While at the scene for this traffic collision on May 25, 2022 I noticed there was a UC Davis Health Clinic on the 1 2 corner of Hutchinson Dr. and Dairy Rd. I noticed on the south west corner of the building a security camera. Also 3 on the north east corner of the building was another security camera. I was later informed by UC Davis Police 4 that this traffic collision was captured on the two above mentioned cameras. On May 26, 2022 I was given a 5 thumb drive by UC Davis Detective E. Lee. The USB thumb drive contained the security video from the Health 6 Clinic. 7 8 I watched the camera angle from the north west corner of the building it depicts the following: 9 10 The camera date stamped was May 25, 2022 at 8:06 hours. It shows a white SUV in the number one position in 11 the #2 lane of east bound Hutchinson. A Grey SUV in the number one lane. 12 There are no bicyclist in the east bound lane of Hutchinson. 13 14 8:06:07 Witness vehicle comes into camera view and is north bound Dairy Rd. in the number 1 position at the 15 limit line. 16 17 8:06:10 Garbage truck comes into camera view and it driving east bound Hutchinson Dr. 18 19 8:06:15 Grey SUV starts moving and makes a left turn. At this time garbage truck is approaching the white SUV 20 and slows down. The garbage truck has the right turn signal activated. 21 22 8:06:18 Garbage truck comes to a stop. 23 24 8:06:19 Bicyclist enters camera view and is riding east on Hutchinson Dr. 25 26 8:06:28 Bicyclist next to vehicle that is directly behind garbage truck. 27 8:06:29 White SUV begins to move east on Hutchinson Dr. 28 29 30 8:06:31 Garbage truck begins to move. Bicyclist is along the right side of truck right in the middle of the truck. 31 32 8:06:33 Garbage truck starts to make right turn. Bicyclist crosses the white solid limit line. 33 34 8:06:34 Garbage truck and bicyclist collide. Point of impact appears to be on the corner of the front bumper on 35 the passenger side. 36 37 8:06:35 Garbage truck is facing south on Dairy Rd. has not completed turn. 38 39 40 8:06:37 Garbage truck completes turn and is now south on Dairy RD. 41 42 8:06:39 Prepared By: Date: Approved By: Date:

DUDLEY, DAVID

[] BODY CAMERA RECORDED

Page 2 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 4 - Security Camera Video from 684 Hutchinson Dr.

1 2 8:06:40 3 4 5 8:06:40:405 6 7 8:06:41 8 9 I then watched the second camera angle which covers north and south bound Dairy Rd. and also the intersection 10 of Hutchinson Dr. and Dairy Rd. 11 12 I started the footage at 08:06:00 It shows a white SUV in the number one position in the #2 lane of east bound 13 Hutchinson. A Grey SUV in the number one lane. There are no bicyclist in the east bound lane of Hutchinson 14 15 8:06:03 Witness vehicle enters the screen north bound on Dairy Rd. 16 17 8:06:10 Garbage Truck (V2) is seen east bound on Hutchinson Dr. by the soccer fields. 18 19 8:06:18 Garbage truck stops behind a White SUV. 20 21 8:06:23 Bicyclist (B1) appears in camera view and is east bound Hutchinson Dr. passing by the soccer fields. 22 23 8:06:29 Garbage truck begins to move. Bicyclist is at the passenger side rear tires. 24 25 8:06:34 Bicycle is now at Garbage truck's passenger side door as truck starts to make right turn. 26 27 8:06:34:199 Front passenger tire of Garbage truck is turned to the right. Bicyclist is in front of the tire, and by the 28 front bumper. 29 30 8:06:34:533 Garbage truck and Bicyclist collide 31 32 8:06:35 Garbage truck is facing south on Dairy Rd. has not completed turn. 33 34 35 8:06:37 Garbage truck completes turn and is now south on Dairy Rd. 36 37 38 8:06:40 39 40 41 8:06:40:405 42 Prepared By: Date: Approved By: Date: 05/30/2022 08/24/2022 DUDLEY, DAVID PYTEL, DARREN

[] CAR CAMERA RECORDED

[] BODY CAMERA RECORDED

Page 3 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 4 - Security Camera Video from 684 Hutchinson Dr.

1 8:06:41 Garbage truck starts to pull to the right side of the 2 roadway. 3 4 8:06:47 Garbage truck comes to a stop. 5 6 8:06:56 Driver (D2) exits the Garbage truck. 7 8 8:07 Driver (D2) runs over to B1 and makes contact. 9 10 11 12 **DISPOSITION:** 13 Attach to main report 14 15 16 17 18 19 20 21

Page 1 22-02347

2600 5TH ST DAVIS, CA 95618 530-747-5400 SUPPLEMENT 5 - Coroner report

On May 26, 2022 I contacted Sacramento County Coroner's Office and spoke with Deputy Caleb Shifflett. I was told an autopsy will be performed on B1. Deputy Shifflett provided me their case number 22-0330, and told me to follow up on a later date for the autopsy findings.

3 4 5

6

7

1 2


On June 20, 2022 I called the Sacramento County Coroner's Office and inquired about the Coroners report for this case. I was told the autopsy had been completed but it along with the coroner's report have not been signed yet. I asked if it listed a cause of death and was told "Blunt force trauma". The deputy I spoke with stated they would send me a copy of the coroner's report once it is completed.

8 9 10

DISPOSITION:

11 Attach to main case.

Prepared By:		Date:	Approved By:		Date:
127	DUDLEY, DAVID	06/20/2022	105	DIAS, TONI	08/01/2022
[] BO	DY CAMERA RECORDED	[] CAR CAMERA RECORDED			



OSP 03 75578

STATE OF CALIFORNIA
FACTUAL DIAGRAM

CHP 555 Page 4(Rev. 1-03	3) OPI 061			Page Z of Z
DATE OF COLLISION (MO. DAY YE	EAR) TIME (2400)	NCIC #	officer l.D.	NUMBER 22-2347

PREPARED BY DUNLEY I.D. NUMBER

REVIEWER'S NAME

MO DAY YEAR